


- (D)** -NH-Sicherungs-Lastschaltleiste 1-3
(GB) -NH Fuse-Switches, vertical design 1-3
(PL) -NH Rozłącznik bezpiecznikowy listwowy n.n 1-3
(ES) -NH Interruptor-Seccionador vertical para fusibles 1-3
(RU) -NH Предохранитель-выключатель нагрузки-разъединитель вертикальной конструкции размера 1-3


(D)

- Sicherungseinsätze und Trennmesser mit versilberten Oberflächen einsetzen.
- Zügig schalten.

(GB)

- Use silver-coated fuse-links and solid links.
- Operate quickly.

(PL)





- Wkładki bezpiecznikowe oraz zwieracze nożowe stosuj wyłącznie srebrzone
- Łączyć szybko

(ES)

- utilizar fusibles de cuchilla con contactos plateados
- rapida maniobra

(RU)

- применять предохранители и разъединительные ножи только с посеребрёнными контактами
- включать и разъединять быстро

 EN/IEC60947-3
 VDE 0660 T107

Montageart 1; Spannungsfrei
Kind of assembly 1; Zero potential

Montageart 2; Montage unter Spannung
Kind of assembly 2; Assembly under voltage
