




- (D)  -NH-Sicherungs-Lastschaltleiste 1-3
 (GB)  -NH Fuse-Switches, vertical design 1-3
 (PL)  -NH Rzutacznik-bezpiecznikowy listwowy n.n 1-3
 (ES)  -NH Interruptor-Seccionador vertical para fusibles 1-3
 (RU)  -NH Предохранитель-выключатель нагрузки-разъединитель вертикальной конструкции размера 1-3

89523-0100_If






- (D)  • Sicherungseinsätze und Trennmesser mit versilberten Oberflächen einsetzen.
 • Zügig schalten.
- (GB)  • Use silver-coated fuse-links and solid links
 • Operate quickly.
- (PL)  • Wkładki bezpiecznikowe oraz zwieracze nożowe stosuj wyłącznie srebrzone
 • Łączyć szybko
- (ES)  • utilizar fusibles de cuchilla con contavtos plateados.
 • rapida maniobra.
- (RU)  • применять предохранители и разъединительные ножи только с посеребрёнными контактами
 • включать и разъединять быстро

EN/IEC60947-3
 VDE 0660 T107



Montageart 1; Spannungsfrei
 Kind of assembly 1; Zero potential



Montageart 2; Montage unter Spannung
 Kind of assembly 2; Assembly under voltage

